CMC SOLUTIONS

To make glazes brushable, add 1.5% dry CMC to 100% dry glaze and mix well dry before adding water.

100 gr.	Dry glaze
1.5 gr.	CMC
70 ml.	Water

For CMC Solutions, add CMC to water and mix or shake in a closed container to submerge the CMC powder in water.

Let stand for 24 hours and then mix to a creamy, smooth state.

This is used as a glaze and stain binder. It can be thinned with double the water to make a spritzing solution to harden a glaze surface for on-glaze brush painting surfaces such as Majolica painting.

1	gallon	batch
CM	IC	300 grams
Wa	ater	1 gallon

1 pint	<u>batch</u>
CMC	38 grams
Water	1 pint

<u>100</u>	ml.	<u>batch</u>
CMC		8 grams
Water		100 ml.